



Popcorn Machine

Instructions:

1. Plug in machine.
2. Turn on Kettle heat switch, kettle motor and exhaust switch.
3. “Test pop” a kettle of corn: place oil measure in kettle with 3 corn kernels; when kernels pop, place remainder of oil, and kernels in kettle; close lid.
4. When popcorn has popped rotate the handle to empty popcorn from kettle; return kettle to the upright position. Make sure the gears are locked in place at the top so that the inside kettle piece continues to turn.
5. Repeat the cycle; subsequent batches are always more flavorful than the initial batch.
6. Turn off kettle heat switch on the final batch when the popcorn breaks over the kettle to eliminate smoke and odor.
7. Turn off kettle heat, kettle motor and exhaust switches.
8. Light switch can stay on until you are finished serving the popcorn.

Tips:

1. Light and warmer switch-turns on heat lamp and strip heater under corn pan.
2. Kettle motor switch-turns on motor that drives kettle agitator shaft.
3. kettle heat switch –turns on heat element inside kettle.

CATUTION:

TO AVOID SERIOUS BURNS!!!

DO NOT TOUCH KETTLE WHILE IT IS HOT!!!!

Cleaning:

1. Just empty kettle and base of all popcorn.
2. We will take care of the rest!

Most of all:

ENJOY YOUR POPCORN!