

I party with...



1707 Route 6 Carmel NY 10512

845-225-9200

www.rentaparty.com

Sno Kone Machine Instructions

1. Plug unit into a properly grounded 120 volt power supply with a 15 amp circuit.
2. Fill ice horn with cubed or chunk ice.
3. While holding MOTOR switch down, apply steady downward pressure to the ice pusher so that the ice presses against the cutter head.
4. Do not force handle
5. Release the MOTOR switch when finished
6. Scoop ice into cone
7. Add flavor syrup
8. ENJOY!

Repeat steps for additional batches.